


HXW2304 Wash Program
 Delta Timer
 1 minute steps
 All transitions occurs within
 the last 5 seconds of
 the 1 minute cycle



STABER INDUSTRIES
 GROVEPORT, OHIO

DESCRIPTION: **Timer Timing Diagram**

APPR'D: _____ DATE: _____ SCALE: 1/10

PART NO: 81382715.06 MATERIAL: _____ DATE: 12/16/98

ALL DIMS & WEIGHTS IN DIMENSIONS UNLESS OTHERWISE SPECIFIED ON THIS DRAWING OR SECOND, THIRD OR FOURTH ANGLE CONVENTION

1 HOLE 2 HOLE 3 HOLE 4 HOLE 5 HOLE 6 HOLE 7 HOLE 8 HOLE 9 HOLE 10 HOLE 11 HOLE 12 HOLE 13 HOLE 14 HOLE 15 HOLE 16 HOLE

STABER INDUSTRIES
 GROVEPORT, OHIO

AFTER INITIAL APPROVAL, NO CHANGES IN DESIGN, MATERIAL, OR METHOD OF MANUFACTURE WILL BE ACCEPTED WITHOUT PRIOR AUTHORIZATION. PART NO. & DATE OF MANUFACTURE MUST BE STAMPED ON OUTSIDE OF EACH CONTAINER/PALLET.